



Consumer Product Recall **Remington Rimfire: Subsonic 22 Long Rifle Ammunition Lot: P25HB4**

Use of this product may result in firearm damage and/or personal injury.

Remington Ammunition has determined that a certain lot code of **Remington Subsonic 22 LR** 100 pack ammunition may contain rounds with an insufficient crimp and improper powder charge. This issue is only associated with lot number: **P25HB4**. Insufficient crimp and improper powder charges could cause high pressure when fired, resulting in firearm damage and/or personal injury.

Description: Remington Subsonic 22 LR
Index Number: S22HPA
Part #: 21137
Lot Code: P25HB4

Lot codes are stamped along the exterior of the individual 100 pack plastic tray and along the exterior of the case pack.

Examples:

LOT NUMBER



Product 100 pack with lot code



LOT NUMBER

Product case with lot code

If you have recently purchased any **Remington Subsonic 22 LR** ammunition with the specific lot number: **P25HB4**, Remington Ammunition will exchange this product at no charge. For questions, or to arrange for the exchange or refund of this **Subsonic 22 LR** ammunition, please contact the Remington Ammunition Customer Service staff at: **1-800-243-9700**.

Remington Ammunition would like to apologize for any inconveniences or concerns that this issue may have created for our customers. We thank you for your continued support of Remington ammunition products.

December 15, 2023